

SERVICE BULLETIN #6002 - MAY, 1986

TO: ALL HARMAN KARDON WARRANTY STATIONS

SUBJECT: TEMPERATURE RISE OF Q651/Q652

MODEL: CD491

To reduce the temperature rise of Q651 and Q652 in the HX Pro Circuit, resistors R675 and R676 (1 M ohm) have been added as indicated below, starting with serial number 03301.

If you receive for service a CD491 with a serial number less than 03301 these two resistors should be installed.

